

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6R - Polo 2010 >/--
 VIN: WVVZZZ6RZDY087210

Odometer Reading: 146855
 License Plate: KBH184MP

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
 Version: V19.00

Serial Number: VB8GJCC01482
 Repair Order Number: --

System Scanned (13)

System	Status/DTC
01 - Engine Control Module 1	 18
02 - Transmission electronics	 4
03 - Brakes 1	 2
04 - Steering Angle Sender	 0
08 - Air Conditioning	 1
09 - Electronic central electric	 2
15 - Airbag	 1
17 - Instrument cluster	 1
19 - Gateway	 0
25 - Anti-Theft Immobilizer	 0
44 - Power Steering	 0
56 - Radio	 3
77 - Telephone	 2

DTC (34)

01 - Engine Control Module 1 (18 DTCs)

DTC	Description	Status
P195000	Coolant fan for coolant difficulty of movement/blocked	Passive/Sporadic
P035400	Ignition Coil D Primary/secondary Circuit	Passive/Sporadic

P056200	System Voltage Low Voltage	Passive/Sporadic
P068A00	ECM/PCM Power Relay De-Energized Performance - Too Early	Active/static
P001100	A Camshaft Position (Bank1) Timing over-advanced or System Performance	Passive/Sporadic
P008700	Fuel rail/system pressure - too low	Passive/Sporadic
P042000	Catalyst system (bank 1) Efficiency below lower limit	Active/static
P226300	Turbocharger/Supercharger Boost System Performance	Active/static
P029900	Turbocharger/supercharger underboost	Passive/Sporadic
P227900	Intake air system leakage	Passive/Sporadic
P030100	Cylinder 1 Misfire detected	Passive/Sporadic
P030300	Cylinder 3 Misfire detected	Passive/Sporadic
P030400	Cylinder 4 Misfire detected	Passive/Sporadic
P130A00	Cylinder suppression	Passive/Sporadic
P030000	Random/multiple cylinder Misfire detected	Passive/Sporadic
P162400	Requirement - malfunction lamp on active	Passive/Sporadic
P044100	EVAP Emission Contr.Sys.Incorrect Purge Flow	Passive/Sporadic
P003300	Turbocharger bypass valve control circuit	Passive/Sporadic

02 - Transmission electronics (4 DTCs)

DTC	Description	Status
P072D:00/01 837:000	Stuck in Gear 2 -	Passive/Sporadic
P177C:07/06 012:007	Clutch 2 Tolerance limit reached - Short circuit to ground	Passive/Sporadic
P072F:00/01 839:000	Stuck in Gear 4 -	Passive/Sporadic
P1779:00/06 009:000	Transmission input shaft 1 Overspeed -	Passive/Sporadic

03 - Brakes 1 (2 DTCs)

DTC	Description	Status
-----	-------------	--------

02214:002	Tire pressure warning - Lower limit not reached	Passive/Sporadic
00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic

08 - Air Conditioning (1 DTC)

DTC	Description	Status
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic

09 - Electronic central electric (2 DTCs)

DTC	Description	Status
00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic

15 - Airbag (1 DTC)

DTC	Description	Status
U112200	Data bus message implausible	Passive/Sporadic

17 - Instrument cluster (1 DTC)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic

56 - Radio (3 DTCs)

DTC	Description	Status
00446:002	Function limitation due to insufficient voltage - Lower limit not reached	Passive/Sporadic
00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic
00871:011	Right front bass speaker - Open circuit	Active/static

77 - Telephone (2 DTCs)

DTC	Description	Status
00446:000	Function limitation due to insufficient voltage -	Passive/Sporadic
00532:002	Supply voltage - Lower limit not reached	Passive/Sporadic

Technician Notes

2016718352

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.