



CONDITION REPORT

Report No: 2016277891

DATE
22/02/2024

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	22/02/2024		M57 Pretoria Road - 1619
Inspection Date	22/02/2024		Kempton Park - GT


Vehicle Data

Vehicle Type	PASSENGER VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	VOLKSWAGEN	Registration Number	JL07CVGP
Model	POLO TSI	Register Number	
VIN	AAVZZZAWZLU025604	Date Of First Licensing	
Engine Number		Last COR	
Doors	5	License Expiry Date	31/01/2024
Color	GREY	Power / Displacement	
Year Model		Paint Finish	M - METALLIC
Km Reading	152,336 KM	Fuel	PETROL
Cab / Body Type	HATCHBACK	Transmission	AUTOMATIC

Vehicle Options & Accessories

Items

VEHICLE INSPECTION



Damage	Repair Way
Switch Electrical Window Winder front left Defective	Repair
Tail Light Left Broken	Replace
Seat Front Right Torn / Cut	Repair
Front Bumper Paintwork • Scratched	Repair
C • Pillar Right Paintwork • Scratched	Replace
Rear Fender Left Paintwork • Scratched	Repair
Door Rear Left Paintwork • Scratched	Repair
Rear bumper Damaged	Repair
Sill Panel Left Paintwork • Scratched	Repair
Body exterior	Signs of spray work done on some body panels.
Body exterior.	Minor dents scratches and stone chips on some pan.
Airbag warning light illuminated.	Repair.
Axle and suspension	Both front control arm bushes covered.
Body exterior.	Some body panels misaligned
Engine	Bottom of engine is fully covered
Undercarriage	Bottom of undercarriage is fully covered
Electronics.	Front wiper blades malt

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU025604

1 / 10



CONDITION REPORT

Report No: 2016277891

DATE
22/02/2024

Brakes

Brake Test Results

	Left	Right		
	Braking Force [KN]	Braking Force [KN]	Axle Weight [KG]	Deceleration [m/s ²]
Front	3.1	3.2	-	
Rear	1.8	2.0	-	
Emergency / Parking	1.5	1.9	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	195/55R16	91V	Falken	Ziex	V	0723	5 mm
Front Right	195/55R16	91V	Falken	Ziex	V	0723	5 mm
Rear Left	195/55R16	91V	Goodyear	Efficient	V	4520	1 mm
Rear Right	195/55R16	91V	Goodyear	Efficient	V	4420	1 mm
Spare	185/65R15	88T	Falken	Sincera	V	//////	5 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive

Battery Flat

Engine number – not possible to verify engine number (not visible without dismantling)

Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Trevino Julius


This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.




CONDITION REPORT

Report No: 2016277891

DATE
22/02/2024


Diagnostic test



Diagnostic test



Diagnostic test



Diagnostic test



FRONT RIGHT CORNER



REAR LEFT CORNER

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU025604

3 / 10



CONDITION REPORT

Report No: 2016277891

DATE
22/02/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU025604
4 / 10



CONDITION REPORT

Report No: 2016277891

DATE
22/02/2024

INTERIOR (FRONT DRIVER DOOR)



DASHBOARD (W/ ENGINE RUNNING)



ODOMETER



90 DEGREE FRONT



90 DEGREE RIGHT



90 DEGREE REAR

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU025604

5 / 10



CONDITION REPORT

Report No: 2016277891

DATE
22/02/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU025604
6 / 10



CONDITION REPORT


Report No: 2016277891

DATE
22/02/2024

90 DEGREE LEFT




LF TYRE TREAD



LR TYRE TREAD



RR TYRE TREAD



RF TYRE TREAD



Sparewheel

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZAWZLU025604

7 / 10



CONDITION REPORT

Report No: 2016277891

DATE
22/02/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU025604
8 / 10




CONDITION REPORT

Report No: 2016277891

DATE
22/02/2024



LICENSE DISC



VIN PLATE OR STICKER



ENGINE 1



ENGINE 2



CHASSIS



Rear end



CONDITION REPORT

Report No: 2016277891

DATE
22/02/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za

VIN: AAVZZZAWZLU025604
10 / 10



CONDITION REPORT

Report No: 2016277891

DATE
22/02/2024

Expansion bottle



Oil cap and dipstick



Automatic



Airbag warning light illuminat



Seat Front Right



Water level



CONDITION REPORT

Report No: 2016277891

DATE
22/02/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016277891

DATE
22/02/2024

Front Bumper



Front Bumper



Front Bumper



Front Bumper



Front Bumper



Door Rear Left



CONDITION REPORT

Report No: 2016277891

DATE
22/02/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016277891

DATE
22/02/2024

Sill Panel Left



Rear Fender Left



Rear bumper



Rear bumper



Rear bumper



Tail Light Left



CONDITION REPORT

Report No: 2016277891

DATE
22/02/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za



CONDITION REPORT

Report No: 2016277891

DATE
22/02/2024

C • Pillar Right



Switch Electrical Window Winder front left

**CONDITION REPORT****Report No: 2016277891****DATE**
22/02/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za