

MFC Auction House
M57 Pretoria Rd, Glenmarais, KEMPTON PARK
Gauteng

DEKRA MFC
M57 Pretoria Rd - 1619
KEMPTON PARK - GT
08610 33572



Assignment

Client	MFC Auction House	Inspection Location	MFC
Requested Date	16/04/2024		M57 Pretoria Road - 1619
Inspection Date	16/04/2024		Kempton Park - GT

Vehicle Data

Vehicle Type	LIGHT LOAD VEHICLE	Registered Owner	MFC AUCTION HOUSE
Manufacturer	FORD	Registration Number	JPY079MP
Model	RANGER	Register Number	
VIN	AFANXXMJ2NJP21561	Date Of First Licensing	
Engine Number		Last COR	
Doors	2	License Expiry Date	30/09/2023
Color	WHITE	Power / Displacement	
Year Model		Paint Finish	C - COMMON
Km Reading	147,143 KM	Fuel	DIESEL
Cab / Body Type	SINGLE CAB	Transmission	MANUAL

Vehicle Options & Accessories

Items


VEHICLE INSPECTION

Damage

Repair Way

Front Bumper Paintwork • Scratched
Front Fender Left Dented
Front Fender Right Dented
Rear Fender Left Paintwork • Scratched
Door Front Left Dented
Tailgate Dented

Repair
Repair
Repair
Repair
Repair
Repair



Brakes

Brake Test Results

	Left	Right	Axle Weight [KG]	Deceleration [m/s ²]
	Braking Force [KN]	Braking Force [KN]		
Front	4.5	4.9	-	
Rear	3.0	2.8	-	
Emergency / Parking	2.6	3	-	

Tyres and Rims

Tyre Specification & Measurement

	Size	Load/Speed Index	Manufacture	Model	Type*	Production Date	Tread Depth (mm)
Front Left	255/70R16	111T	Continental	Contact	V	2921	3 mm
Front Right	255/70R16	111T	Continental	Contact	V	2921	3 mm
Rear Left	255/70R16	111T	Continental	Contact	V	2921	3 mm
Rear Right	255/70R16	111T	Continental	Contact	V	2921	3 mm
Spare	255/70R16	111T	Continental	Contact	V	////	5 mm

* Tyre Legend: V=Virgin, R=Recap

Diagnostic

During the diagnostic no active error messages were detected. (See also attached Diagnostic Report. For more information regarding the Fault Codes (DTC) and the recommended rectifications please contact the workshops of the vehicle manufacture).

Inspection Conditions

No Test Drive
Battery Flat
Engine number – not possible to verify engine number (not visible without dismantling)
Inspection conditions for the vehicle inspection were sufficient

Comments

General Comments: ACCORDING TO THE AGE AND MILEAGE OF THE VEHICLE, NORMAL WEAR AND TEAR MARKS ARE VISIBLE ON THE INTERIOR, EXTERIOR, ELECTRICAL AND MECHANICAL PARTS.

Concluding Remarks

THIS REPORT HAS BEEN DRAWN UP IMPARTIALLY AND TO THE BEST OF OUR KNOWLEDGE

Technician

Andrick Wymers

This document was created electronically and is valid without signature.

General Remarks: The DEKRA Condition Report Inspection is a visual and functional check of all the items listed inside the report. DEKRA is not liable for concealed and hidden defects. DEKRA doesn't check: oil and fuel consumption, source of a leak if the area is dirty, oil pump strainer for any build-up of sludge, operation of cassette players or compact disc players, sound or radio reception, alarm systems, cylinder compression. We don't dismantle, remove or strip any part of the vehicle. Road testing is carried out within the immediate confines of the inspection location. This condition report is valid only for the described vehicle and the described condition at the time of inspection. DEKRA Terms & Conditions apply.



REAR LEFT CORNER



FRONT RIGHT CORNER



90 DEGREE RIGHT



90 DEGREE LEFT



90 DEGREE FRONT



90 DEGREE REAR



CONDITION REPORT

Report No: 2016343347

VIN: AFANXXMJ2NJP21561

DATE

16/04/2024



ODOMETER




DASHBOARD (W/ ENGINE RUNNING)




INTERIOR (FRONT DRIVER DOOR)



Manual



LF TYRE TREAD



LR TYRE TREAD



RF TYRE TREAD



RR TYRE TREAD



Expenditure bottle



Oil cap and dipstick



Spare wheel



ENGINE 1

VIN: AFANXXMJ2NJP21561

7 / 8



ENGINE 2



CHASSIS

VIN: AFAFNXY20NJP21561
8 / 8



VIN PLATE OR STICKER



LICENSE DISC



SHOCK & BRAKE REPORT



DIAGNOSTIC REPORT PAGE 1



DIAGNOSTIC REPORT PAGE 2



Water level




Front Fender Right



Front Bumper



Front Bumper



Front Fender Left



Door Front Left



Rear Fender Left



Tailgate



CONDITION REPORT

Report No: 2016343347

DATE
16/04/2024

DEKRA Automotive (PTY) Ltd.
97 Willem Cruywagen Ave
Klerksoord, Pretoria, 0200
Phone: 012 542 4867
www.dekraauto.co.za