Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261113131601
Test Time: 2026-11-13 13:16:01
Technician: Andrick

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/60/61/64 - Polo/Vento 2010 >/--
VIN: AAVZZZ6RZGU038919

Odometer Reading: 110152
License Plate: FB89RJGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (5)

System	Status/DTC
01 - Engine Control Module 1	0
03 - Brakes 1	0
15 - Airbag	0
17 - Instrument cluster	0
44 - Power steering	0

DTC (0)

Technician Notes

2017325401

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.