



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250505150554
Test Time: 2025-05-05 15:05:54
Technician: Travino

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/60/61/64 - Polo/Vento 2010 >/--
VIN: AAVZZZ6RZHU109170

Odometer Reading: 107426
License Plate: HC84JGGP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V22.00

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(5)

System	Status/DTC
01 - Engine Control Module 1	 5
03 - Brakes 1	 0
15 - Airbag	 1
17 - Instrument cluster	 0
44 - Power Steering	 0

DTC (6)

01 - Engine Control Module 1 (5 DTCs)

DTC	Description	Status
P308800	Starter relay Electrical fault in circuit	Passive/Sporadic
P157000	Engine control unit disabled	Passive/Sporadic
P030000	Random/multiple cylinder Misfire detected	Passive/Sporadic
P030400	Cylinder 4 Misfire detected	Passive/Sporadic
P125000	Fuel level too low	Passive/Sporadic

15 - Airbag (1 DTC)

DTC	Description	Status
B13BCF2	Multiple collision brake No function	Passive/Sporadic

Technician Notes
2016865442



Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.