



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250819103909
Test Time: 2025-08-19 10:39:09
Technician: Travino

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6RS - Polo Vivo 2018 >/--
VIN: AAVZZZ6RZMU004358

Odometer Reading: 135807
License Plate: FMG844L

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V23.00

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(9)

System	Status/DTC
01 - Engine Control Module 1	 3
03 - Brakes 1	 1
09 - Electronic central electric	 1
15 - Airbag	 1
17 - Instrument cluster	 0
19 - Gateway	 1
25 - Anti-Theft Immobilizer	 1
44 - Power Steering	 0
56 - Radio	 1

DTC (9)

01 - Engine Control Module 1 (3 DTCs)

DTC	Description	Status
P1603:00/0-5635:000	Ctrl. module faulty	Passive/Sporadic
P0303:00/0-0771:000	Cyl.3 Misfire Detected	Passive/Sporadic
P0300:00/0-0768:000	Random/Multiple Cylinder Misfire Detected	Active/static

03 - Brakes 1 (1 DTC)

DTC	Description	Status
U010000	Lost Communication with ECM/PCM	Passive/Sporadic

09 - Electronic central electric (1 DTC)



DTC	Description	Status
01758:011	Lamps for brake lights - Open circuit	Active/static

15 - Airbag (1 DTC)

DTC	Description	Status
U112100	Data bus message missing	Passive/Sporadic

19 - Gateway (1 DTC)

DTC	Description	Status
01314:004	Engine control unit - No signal/communication	Passive/Sporadic

25 - Anti-Theft Immobilizer (1 DTC)

DTC	Description	Status
B104A00	Engine control unit 1/power electronics 4 not authorized	Passive/Sporadic

56 - Radio (1 DTC)

DTC	Description	Status
02873:004	Rearview camera system control module - No signal/communication	Passive/Sporadic

Technician Notes
2016984022

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.