Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6RS - Polo Vivo 2018 >/--
VIN: AAVZZZ6RZNU004252

Odometer Reading: 89921
License Plate: KH22LGGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (11)

System	Status/DTC
01 - Engine Control Module 1	1
02 - Transmission electronics	3
03 - Brakes 1	2
04 - Steering Angle Sender	0
09 - Electronic central electric	1
15 - Airbag	0
17 - Instrument cluster	0
19 - Gateway	0
25 - Immobilizer	0
44 - Power steering	0
56 - Radio	1

DTC (8)

01 - Engine Control Module 1 (1 DTC)

DTC	Description	Status
P1652:00/05 714:000	Read DTC memory of transmission CM	Active/static

02 - Transmission electronics (3 DTCs)

DTC	Description	Status
P070600	Transmission range sensor A circuit range/performance	Passive/Sporadic
P070900	Transmission Range Sensor 'A' Circuit Intermittent	Passive/Sporadic
U010000	Lost Communication with ECM/PCM	Passive/Sporadic

03 - Brakes 1 (2 DTCs)

DTC	Description	Status
C114602	TPMS ,Signal error	Active/static
U102600	Transmission control module ,Check event memory	Active/static

09 - Electronic central electric (1 DTC)

DTC	Description	Status
01758:011	Lamps for brake lights - Open circuit	Active/static

56 - Radio (1 DTC)

DTC	Description	Status
01044:000	Control module incorrectly coded	Passive/Sporadic

Technician Notes

2017323374

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.