Nedbank MFC **Auction House**A division of **SNEDBANK**

Shop Name: Dekra MFC Auction House

Tel: --Email: --

Address: MFC AUCTION HOUSE

M57 PRETORIA ROAD KEMPTON PARK Report ID: MAXIA20241018150245 Test Time: 2024-10-18 15:02:45

Technician: Travino

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6RS - Polo Vivo 2018 >/--

VIN: AAVZZZ6RZNU014639

Customer Information

Name: Dekra MFC AUCTION HOUSE

Device information

Scanner: MaxiSys MS906 BT

Version: V21.00

Odometer Reading: 91451 License Plate: KR12YJGP

Tel: 0861033572

Serial Number: VB8GJCC01514

Repair Order Number: --

System Scanned(9)

System	Status/DTC
01 - Engine Control Module 1	© 6
03 - Brakes 1	② 0
09 - Electronic central electric	Q 2
15 - Airbag	② 0
17 - Instrument cluster	Q 2
19 - Gateway	② 0
25 - Anti-Theft Immobilizer	Q 1
44 - Power Steering	② 0
56 - Radio	② 0

🔼 DTC (11)

01 - Engine Control Module 1 (6 DTCs)

DTC	Description	Status
U0151:00/49 489:000	Lost Communication With Restraints Control Module	Passive/Sporadic
U0121:00/49 441:000	Lost Communication With Anti-Lock Brake System (ABS) Control Module	Passive/Sporadic
P0481:00/01 153:000	Cooling Fan 2 Control Circuit	Passive/Sporadic
U0002:00/49 154:000	Databus drivetrain No communication	Passive/Sporadic
P0300:00/00 768:000	Random/Multiple Cylinder Misfire Detected	Passive/Sporadic

www.autel.com

MaxiSys MS906 BT

Page 1

/Volkswagen/6RS -	Polo Vivo 2018 >	Test Time: 2024-10-18 15:02:45	Report ID: MAXIA20241018150245
P0303:00/00 771:000	Cyl.3 Misfire Detected		Passive/Sporadic
09 - Electronic c	entral electric (2 DTCs)		
DTC	Description		Status
00975:011	Rear window defogger - Open circuit		Active/static
00446:002	Function limitation due to insufficient voltage - Lower limit not reached		Passive/Sporadic
17 - Instrument	cluster (2 DTCs)		
DTC	Description		Status
U111100	Function restriction caus	sed by missing message	Passive/Sporadic
U101100	Supply voltage Voltage too low		Passive/Sporadic
25 - Anti-Theft I	mmobilizer (1 DTC)		
DTC	Description		Status
B104A00	Engine control unit 1/po	wer electronics 4 not authorized	Passive/Sporadic
Technician Not 2016577168	ces		
	Customer name:		
		Technician:	
		Date:	

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



MaxiSys MS906 BT Page 2