Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261105094328
Test Time: 2026-11-05 09:43:28
Technician: Sbu

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6S - Polo VIVO 2010 >/--
VIN: AAVZZZ6SZCU019464

Odometer Reading: 372681
License Plate: CK70FDGP

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V25.00

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (1)

System	Status/DTC
44 - Power steering	2

DTC (2)

44 - Power steering (2 DTCs)

DTC	Description	Status
U140000	Function restriction ,due to low voltage	Active/static
U101100	Supply voltage ,Voltage too low	Passive/Sporadic

Technician Notes

2017321514

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.