

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6S - Polo VIVO 2010 >/--
VIN: AAVZZZ6SZCU020848

Odometer Reading: 248639
License Plate: BT11MTGP

Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V19.50

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned(10)

System	Status/DTC
01 - Engine Control Module 1	1
03 - Brakes 1	0
08 - Air Conditioning	2
09 - Electronic central electric	1
15 - Airbag	1
17 - Instrument cluster	1
19 - Gateway	0
25 - Anti-Theft Immobilizer	0
44 - Power Steering	1
46 - Comfort System Central Control Module	1

DTC (8)

01 - Engine Control Module 1 (1 DTC)

DTC	Description	Status
16500:000	Engine Coolant Temperature Sensor 1 Circuit Range/Performance	Passive/Sporadic

08 - Air Conditioning (2 DTCs)

DTC	Description	Status
00898:030	Activation A/C compressor - Open circuit/short circuit to B+	Active/static
01317:079	Instrument cluster control module - Please read DTC	Active/static

09 - Electronic central electric (1 DTC)

DTC	Description	Status
01598:007	Drive battery voltage - Signal too low	Passive/Sporadic

15 - Airbag (1 DTC)

DTC	Description	Status
00532:007	Supply voltage - Signal too low	Passive/Sporadic

17 - Instrument cluster (1 DTC)

DTC	Description	Status
00779:030	Outside temperature sensor - Open circuit/short circuit to B+	Active/static

44 - Power Steering (1 DTC)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic

46 - Comfort System Central Control Module (1 DTC)

DTC	Description	Status
01330:053	Comfort system central control module - Voltage supply too low	Passive/Sporadic

Technician Notes

2016298205

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.