



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250701121715
Test Time: 2025-07-01 12:17:15
Technician: Werner

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6S - Polo VIVO 2010 >--
VIN: AAVZZZ6SZEU031442
Odometer Reading: 325057
License Plate: HJ26KTGP

Customer Information

Name: Dekra MFC AUCTION HOUSE
Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V22.50
Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(10)

System	Status/DTC
01 - Engine Control Module 1	2
03 - Brakes 1	0
09 - Electronic central electric	1
15 - Airbag	1
17 - Instrument cluster	0
19 - Gateway	0
25 - Anti-Theft Immobilizer	0
44 - Power Steering	1
46 - Comfort System Central Control Module	0
56 - Radio	0

DTC (5)

01 - Engine Control Module 1 (2 DTCs)

DTC	Description	Status
P1672:00/0-5746:000	Fan 1 control circuit Open circuit/short circuit to ground	Passive/Sporadic
P0118:00/0-0280:000	Engine Coolant Temperature Sensor 1 Circuit High	Active/static

09 - Electronic central electric (1 DTC)

DTC	Description	Status
01598:007	Drive battery voltage - Signal too low	Passive/Sporadic

15 - Airbag (1 DTC)



DTC	Description	Status
00532:007	Supply voltage - Signal too low	Passive/Sporadic

44 - Power Steering (1 DTC)

DTC	Description	Status
U101100	Supply voltage Voltage too low	Passive/Sporadic

Technician Notes
2016931345

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.