

Volkswagen VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Volkswagen/6S - Polo VIVO 2010 >/--
VIN: AAVZZZ6SZGU030895

Odometer Reading: 200633
License Plate: KVM657NW

Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V22.50

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned(11)

System	Status/DTC
01 - Engine Control Module 1	 0
03 - Brakes 1	 0
09 - Electronic central electric	 1
15 - Airbag	 1
17 - Instrument cluster	 0
19 - Gateway	 0
25 - Anti-Theft Immobilizer	 0
44 - Power Steering	 0
45 - Interior Monitoring	 0
46 - Comfort System Central Control Module	 0
56 - Radio	 0

DTC (2)

09 - Electronic central electric (1 DTC)

DTC	Description	Status
01598:007	Drive battery voltage - Signal too low	Passive/Sporadic

15 - Airbag (1 DTC)

DTC	Description	Status
00532:007	Supply voltage - Signal too low	Passive/Sporadic

Technician Notes

2016904811

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.