



Shop: DEKRA MFC
Tel: --
Email: --
Address: MFC Auction House
Kempton Park

Report ID: MAXIA20231221134725
Test Time: 2023-12-21 13:47:25
Technician: Travino

Isuzu VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Isuzu/TF series/D-MAX/--
VIN: ACVMRRAR5J4021120
Odometer Reading: 181952
License Plate: HT06CWGP


Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE
Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V5.30
Serial Number: VB8GJCC01482
Repair Order Number: --

System Scanned(1)

System	Status/DTC
Meter	 0

DTC (0)

Technician Notes

2016209209

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.