Shop Name: –
Tel: --
Email: --
Address: --

Report ID: MAXIA20261113105348
Test Time: 2026-11-13 10:53:48
Technician: Andrick

Chevrolet VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Chevrolet/Spark/--
VIN: ADMMF48DLC4627636
Odometer Reading: 207500.0km
License Plate: KMP255MP

Customer Information

Name: MFC NEDBANK
Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V34.10
Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (3)

System	Status/DTC
Electronic brake control module	1
Inflatable restraint sensing and diagnostic module	1
Instrument cluster	0

DTC (2)

Electronic brake control module (1 DTC)

DTC	Description	Status
C0800:03	Control module power circuit low voltage	DTC history status : History Since DTC clear : Passed and failed Last test : Passed This ignition cycle : Passed MIL status : Not requested

Inflatable restraint sensing and diagnostic module (1 DTC)

DTC	Description	Status
B0012:0D	Steering wheel air bag deployment loop high resistance	DTC history status : History DTC current status : Current MIL status : Requested

Technician Notes

2017325354

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.