

Shop: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20240726073954
Test Time: 2024-07-26 07:39:54
Technician: Andrick

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/NP300/--
VIN: ADNALGD22ZR072418
Odometer Reading: 308978
License Plate: DL96BWGP


Customer Information

Name: Dekra MFC AUCTION HOUSE
Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V9.90
Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(1)

System	Status/DTC
Engine	 0

DTC (0)

Technician Notes

2016468770

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.