



Shop: DEKRA MFC
Tel: --
Email: --
Address: MFC Auction House
Kempton Park

Report ID: MAXIA20231214131518
Test Time: 2023-12-14 13:15:18
Technician: Sbu

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/NP 300/--

VIN: ADNAPGD22ZR127180

Odometer Reading: 54269

License Plate: JN73FMGP

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information




Scanner: MaxiSys MS906 BT

Version: V9.41

Serial Number: VB8GJCC01482

Repair Order Number: --

System Scanned(3)

| System | Status/DTC |
|---------|---|
| Engine |  0 |
| Air bag |  0 |
| BCM |  1 |

DTC (1)

BCM (1 DTC)

| DTC | Description | Status |
|-------|---------------------------|--------|
| U1000 | CAN communication circuit | Past |

Technician Notes

2016203861

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

