



Shop: DEKRA MFC
Tel: --
Email: --
Address: MFC Auction House
Kempton Park

Report ID: MAXIA20240104133433
Test Time: 2024-01-04 13:34:33
Technician: Sbu

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/NP200/--
VIN: ADNUSN1D5U0154645

Odometer Reading: 95228
License Plate: HX72GTGP

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE




Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V9.41

Serial Number: VB8GJCC01482
Repair Order Number: --

System Scanned(3)

System	Status/DTC
ABS	 0
Air bag	 0
BCM	 6

DTC (6)

BCM (6 DTCs)

DTC	Description	Status
P0000	Front windshield wiper park circuit	
000200	Please refer to vehicle service manual.	
402000	Please refer to vehicle service manual.	
P0000	Siren circuit	
090300	Please refer to vehicle service manual.	
004002	Please refer to vehicle service manual.	



Technician Notes

2016218774

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.