



Shop: DEKRA MFC
Tel: --
Email: --
Address: MFC Auction House
Kempton Park

Report ID: MAXIA20240219095935
Test Time: 2024-02-19 09:59:35
Technician: Sbu

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/NP200/--
VIN: ADNUSN1D5U0180197

Odometer Reading: 74516
License Plate: JR23PWGP

Customer Information

Name: --
Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V9.50
Serial Number: VB8GJCC01482
Repair Order Number: --

System Scanned(2)

System	Status/DTC
Air bag	 0
BCM	 5

DTC (5)

BCM (5 DTCs)

DTC	Description	Status
000100	Front windshield wiper park circuit	
402002	Please refer to vehicle service manual.	
004002	Please refer to vehicle service manual.	
P0000	Siren circuit	
P0000	Decoder -> ring connection	

Technician Notes

2016272800

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

