



Shop: DEKRA MFC
Tel: --
Email: --
Address: MFC Auction House
Kempton Park

Report ID: MAXIA20240116134041
Test Time: 2024-01-16 13:40:41
Technician: Werner

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/NP200/--

VIN: ADNUSN1D5U0214852

Odometer Reading: 14464

License Plate: LC29BTGP

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

Version: V9.50

Serial Number: VB8GJCC01482

Repair Order Number: --



System Scanned(2)

System	Status/DTC
Air bag	0
BCM	5



DTC (5)

BCM (5 DTCs)

DTC	Description	Status
000100	Front windshield wiper park circuit	
002000	Please refer to vehicle service manual.	
0B0D00	Please refer to vehicle service manual.	
004002	Siren circuit	
004002	Please refer to vehicle service manual.	

Technician Notes

2016230677

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

