



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250515144219
Test Time: 2025-05-15 14:42:19
Technician: Travino

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/NP200/--
VIN: ADNUSN365U0160767

Odometer Reading: 237246
License Plate: HX25YJGP

Customer Information

Name: Dekra MFC AUCTION HOUSE





Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V10.20

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(4)

System	Status/DTC
Engine	 2
Air bag	 1
Electric Power Steering (EPS)/DAST 3	 1
BCM	 4

DTC (8)

Engine (2 DTCs)

DTC	Description	Status
P0380	Preheating unit diagnosis connection	Current
P3264	Water in diesel warning lamp circuit	Past

Air bag (1 DTC)

DTC	Description	Status
B1042	ECU supply voltage	Past

Electric Power Steering (EPS)/DAST 3 (1 DTC)

DTC	Description	Status
560148	Please refer to vehicle service manual.	

BCM (4 DTCs)

DTC	Description	Status
000100	Please refer to vehicle service manual.	
042002	Please refer to vehicle service manual.	
010100	Please refer to vehicle service manual.	
004002	Please refer to vehicle service manual.	

Technician Notes

2016879026



Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.