



Shop: DEKRA MFC
Tel: --
Email: --
Address: MFC Auction House
Kempton Park

Report ID: MAXIA20240108104812
Test Time: 2024-01-08 10:48:12
Technician: Travino

Nissan VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Nissan/NP200/--
VIN: ADNUSN365U0188001
Odometer Reading: 77874
License Plate: KSN522MP





Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE
Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V9.41
Serial Number: VB8GJCC01482
Repair Order Number: --

System Scanned(4)

System	Status/DTC
Engine	 0
Air bag	 0
Electric Power Steering (EPS)/DAST 3	 0
BCM	 6

DTC (6)

BCM (6 DTCs)

DTC	Description	Status
P0000	Front windshield wiper park circuit	
000100	Please refer to vehicle service manual.	
002000	Please refer to vehicle service manual.	
P0000	Siren circuit	
040200	Please refer to vehicle service manual.	
004002	Please refer to vehicle service manual.	



Technician Notes

2016221031

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.