Ford VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Ford/Ranger / Mazda B-Series / Troller/--
VIN: AFAPXXMJ2PLT57050

Odometer Reading: 57049
License Plate: KLL964NW

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V9.31

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (14)

System	Status/DTC
PCM(Powertrain control module)	0
TCM(Transmission control module)	0
ABS(Anti-lock brake system)	0
RCM(Restraint control module)	0
IPC(Instrument panel control module)	0
ACM(Audio control module)	0
BdyCM(Body control module) ADAS	8
FCIM(Front controls interface module)	0
GWM(Gateway module A)	0
PAM(Parking aid module) ADAS	1
PSCM(Power steering control module)	0
RTM(Radio transceiver module)	0
SCCM(Steering column control module)	0
TRM(Trailer module)	0

DTC (9)

BdyCM(Body control module) (8 DTCs)

DTC	Description	Status
B109B:15-48	License Plate Light	CMDTCs
B10F3:15-48	Left front position lamp	CMDTCs
B10F4:15-48	Right front position lamp	CMDTCs
B1247:15-48	Left Rear Turn Indicator	CMDTCs

B1248:15-48	Right Rear Turn Indicator	CMDTCs
B124A:15-0A	Right Daytime Running Light	CMDTCs
B1277:15-48	Reverse Lamp	CMDTCs
B1313:15-08	Interior Lighting Output	CMDTCs

PAM(Parking aid module) (1 DTC)

DTC	Description	Status
B1B48:96-2B	Left Rear Outer Sensor	CMDTCs

Technician Notes

2017324750

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.