AUTEĽ

Shop: DEKRA MFC

Tel: --Email: --

Address: MFC Auction House

Kempton Park

Report ID: MAXIA20240216113343 Test Time: 2024-02-16 11:33:43

Technician: Andrick

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Corolla/--VIN: AHTBB0JE700005552

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Device information

Scanner: MaxiSys MS906 BT

Version: V9.21

Odometer Reading: 192708km License Plate: DK07XPGP

Tel: 0861033572

Serial Number: VB8GJCC01482

Repair Order Number: --

🔁 System Scanned(8)

System	Status/DTC
Engine and ECT	Q 2
SRS airbag	Q 2
Main body	③ 3
Driver door motor	O
Air conditioner	Q 1
Cruise control APAS	② 0
EMPS	O
Immobilizer	O

DTC(8)

Engine and E	ECT (2 DTCs)	
DTC	Description	Status
P1604	Startability fault	Current
P1604	Startability fault	History
SRS airbag (2 DTCs)	
DTC	Description	Status
B1821	Side squib (right) circuit open	Current
B1821	Side squib (right) circuit open	History
Main body (3 DTCs)		
DTC	Description	Status
U0100	Lost communication with ECM/PCM/EV "A"	History

www.autel.com

MaxiSys MS906 BT

Page 1

/Toyota/Corolla	Test Time: 2024-02-16 11:33:43	Report ID: MAXIA20240216113343	
U0101	Lost communication with transmission control module (TCM)	History	
U0151	Lost communication with restraints control module	History	
Air conditioner (1 DTC)			
DTC	Description	Status	
U0100	Lost communication with ECM/PCM/EV "A"	History	
Technician Notes			

2016271058

Customer name:	
Technician:	
Date:	

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



MaxiSys MS906 BT Page 2