Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Corolla/--
VIN: AHTBF8JE101006922

Odometer Reading: 94899km
License Plate: FZW208L

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V11.90

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (9)

System	Status/DTC
Engine and ECT	0
ABS/VSC/TRC	5
SRS airbag	2
Combination meter	1
Main body	3
Driver door motor	0
Air conditioner	1
EMPS	0
Radar cruise 1 ADAS	0

DTC (12)

ABS/VSC/TRC (5 DTCs)

DTC	Description	Status
C1201	Engine/EV control system malfunction	History
C1241	Low or high power supply voltage	History
C1425	Stop switch circuit open	History
C1434	Steering angle sensor (SAS) output	History
C1445	Vehicle driven with steering angle sensor (SAS) not initialized	History

SRS airbag (2 DTCs)

DTC	Description	Status
B1615	Left front airbag sensor	Current
B1615	Left front airbag sensor	History

Combination meter (1 DTC)

DTC	Description	Status
B1507	Turn signal circuit open	History

Main body (3 DTCs)

DTC	Description	Status
U0100	Lost communication with ECM/PCM/EV "A"	History
U0101	Lost communication with transmission control module (TCM)	History
U0151	Lost communication with restraints control module	History

Air conditioner (1 DTC)

DTC	Description	Status
U0100	Lost communication with ECM/PCM/EV "A"	History

Technician Notes

2017324453

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.