

Shop Name: --Tel: --Email: --Address: --

Report ID: MAXIA20250604091554 Test Time: 2025-06-04 09:15:54

Technician: Travino

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Corolla/--VIN: AHTLB52E203144227 Odometer Reading: 178138km License Plate: KK56FFGP

Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01509 Repair Order Number: --

Version: V11.30

🔁 System Scanned(9)

System	Status/DTC
Engine and ECT	② 0
ABS/VSC/TRC	Q 1
SRS airbag	② 0
Main body	② 0
Driver door motor	② 0
Air conditioner	② 0
Theft deterrent	② 0
EMPS	② 0
Radar cruise 1	A®AS



ABS/VSC/TRC (1 DTC)

DTC	Description	Status
C1241	Low or high power supply voltage	Current

Technician Notes

2016900502

Customer name:	
Technician:	
Date:	

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.



MaxiSys MS906 BT

Page 1