



Shop: DEKRA MFC
Tel: --
Email: --
Address: MFC Auction House
Kempton Park

Report ID: MAXIA20231222151720
Test Time: 2023-12-22 15:17:20
Technician: Werner

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Corolla/--
VIN: AHTLB52E903134634

Odometer Reading: 85547
License Plate: FLT661L

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE








Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V9.10

Serial Number: VB8GJCC01482
Repair Order Number: --

System Scanned(7)

System	Status/DTC
Engine and ECT	 0
SRS airbag	 0
Main body	 0
Driver door motor	 0
Air conditioner	 0
Cruise control	 0
Immobilizer	 0

DTC (0)

Technician Notes

2016211814

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

