

Shop: --Tel: --Email: --

Address: --

Report ID: MAXIA20240502084507 Test Time: 2024-05-02 08:45:07

Technician: Sbu

Toyota VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Toyota/Hiace/Ventury/--VIN: AHTSS22P307147397

Customer Information Name: MFC Dekra Nedbank Auction House

Device information

Scanner: MaxiSys MS906 BT

Version: V9.21

Odometer Reading: 40812km License Plate: LD49XFGP

Tel: 0861033572

Serial Number: VB8GJCC01509

Repair Order Number: --

	System	Scanned(5)
--	---------------	----------	----

System	Status/DTC
Engine and ECT	② 0
ABS/VSC/TRC	② 0
SRS airbag	② 0
Combination meter	Q 1
Immobilizer	② 0
MDTC(1)	

🖴 DIC(I)

Combination meter (1 DTC)

DTC	Description	Status
B1507	Turn signal circuit open	History

Technician Notes

2016362509

Customer name:	
Technician:	
Date [.]	

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.