

Mazda VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Mazda/AXELA / MAZDA3/--
VIN: JM6BL10Z2C0305004

Odometer Reading: 222391
License Plate: JH82BKGP

Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V8.30

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned(8)

System	Status/DTC
PCM (Powertrain Control Module)	 1
ABS (Anti-lock Brake System)	 4
RCM (Restraint Control Module)	 0
IC (Instrument Cluster)	 0
EPS (Electronic-Controlled Power Steering)	 0
ACU(Audio Control Unit)	 0
BCM/GEM(Body Control Module / Generic Electronic Module)	  0
MID (Multi-Information Display)	 0

DTC (5)

PCM (Powertrain Control Module) (1 DTC)

DTC	Description	Status
P0328:00-AC	Knock/Combustion Vibration Sensor A Circuit High	CMDTCs

ABS (Anti-lock Brake System) (4 DTCs)

DTC	Description	Status
C0031:01-20	Left Front Wheel Speed Sensor	CMDTCs
C0034:01-20	Right Front Wheel Speed Sensor	CMDTCs
U3003:16-68	Battery Voltage	CMDTCs
U3003:17-2B	Battery Voltage	CMDTCs

Technician Notes

2016353244

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.