



Shop Name: Dekra MFC Auction House  
Tel: --  
Email: --  
Address: MFC AUCTION HOUSE  
M57 PRETORIA ROAD  
KEMPTON PARK

Report ID: MAXIA20250602152010  
Test Time: 2025-06-02 15:20:10  
Technician: Andrick

# Hyundai VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Hyundai/H-100 Truck(HR)/--  
VIN: KMFZBX7BLEU984765  
Odometer Reading: 313949  
License Plate: CP61KKG


## Customer Information

Name: Dekra MFC AUCTION HOUSE  
Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT  
Version: V13.87  
Serial Number: VB8GJCC01514  
Repair Order Number: --

## System Scanned( 1 )

System	Status/DTC
ENG (Engine)	 0

## DTC ( 0 )

## Technician Notes

2016899635

Customer name: \_\_\_\_\_  
Technician: \_\_\_\_\_  
Date: \_\_\_\_\_

Note:Please save a copy of this report for your records.