

# Hyundai VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Hyundai/H-100 Truck(HR)/--

VIN: KMFZBX7BLPU019805

Odometer Reading: 118383

License Plate: FYS419L

## Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT

Version: V14.00

Serial Number: VB8GJCC01509

Repair Order Number: --

## System Scanned ( 1 )

System	Status/DTC
ENG (Engine)	0

## DTC ( 0 )

## Technician Notes

2017219023

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.