



Shop Name: Dekra MFC Auction House  
Tel: --  
Email: --  
Address: MFC AUCTION HOUSE  
M57 PRETORIA ROAD  
KEMPTON PARK

Report ID: MAXIA20250407130110  
Test Time: 2025-04-07 13:01:10  
Technician: Andrick

# Hyundai VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Hyundai/Accent(RB)/--  
VIN: KMHCT41DLKU473728

Odometer Reading: 85261  
License Plate: JJ98YMGP

## Customer Information

Name: Dekra MFC AUCTION HOUSE








Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT  
Version: V13.86

Serial Number: VB8GJCC01514  
Repair Order Number: --

## System Scanned( 7 )

System	Status/DTC
ENG (Engine)	 0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 1
AB (Airbag)	 0
IMMO (Immobilizer)	 0
CODE (Transmitter Code Saving)	 0
EPS (Motor Driven Power Steering)	 0
BCM (Body Control)	 0

## DTC ( 1 )

### ABS/ESP (Anti Lock Brake/Electronic Stability Program) ( 1 DTC )

DTC	Description	Status
C1604	ECU hardware Error	History

## Technician Notes

2016832904

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

