

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/H-1/iMAX/iLOAD/Grand starex(TQ)/--
VIN: KMHWH81KMGU801461Odometer Reading: 264302
License Plate: FGT291L

Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V13.50Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned(7)

System	Status/DTC
ENG (Engine)	 5
A/T (Transaxle)	 0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 1
AB (Airbag)	 2
IMMO (Immobilizer)	 0
CODE (Transmitter Code Saving)	 0
A/C (Air Conditioner)	 0

DTC (8)

ENG (Engine) (5 DTCs)

DTC	Description	Status
P0087	Fuel rail/System pressure too low	History
P0103	Mass or volume air flow 'A' circuit input high	Active
P0113	Intake air temperature (IAT) sensor 1 circuit input high	Active
P0183	Fuel temperature sensor 'A' circuit input high	Active
P0532	A/C Refrigerant pressure sensor 'A' circuit input low	Active

ABS/ESP (Anti Lock Brake/Electronic Stability Program) (1 DTC)

DTC	Description	Status
C1203	Right front vehicle speed sensor (VSS) circuit open or short	Active

AB (Airbag) (2 DTCs)

DTC	Description	Status
-----	-------------	--------

B1102:00	Battery voltage low	History
B1378:00	Front driver side airbag (DSAB) resistance too high	History

Technician Notes

2016395143

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.