

# Kia VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Kia/Picanto/Morning (JA)/--  
VIN: KNAB2511LKT401009

Odometer Reading: 118048  
License Plate: JP32ZSGP

## Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT  
Version: V13.87

Serial Number: VB8GJCC01509  
Repair Order Number: --

## System Scanned( 6 )

| System                            | Status/DTC                                                                              |
|-----------------------------------|-----------------------------------------------------------------------------------------|
| ENG (Engine)                      |  0   |
| AB (Airbag)                       |  1   |
| CLU (Cluster Module)              |  0   |
| A/C (Air Conditioner)             |  0   |
| EPS (Motor Driven Power Steering) |  0 |
| IMMO (Immobilizer)                |  0 |

## DTC ( 1 )

### AB (Airbag) ( 1 DTC )

| DTC      | Description         | Status  |
|----------|---------------------|---------|
| B1102:00 | Battery voltage low | History |

## Technician Notes

2016903345

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note:Please save a copy of this report for your records.