



Shop: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20240702133457
Test Time: 2024-07-02 13:34:57
Technician: Sbu

Kia VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Kia/Rio(YB)/--
VIN: KNADB514LM6493345
Odometer Reading: 83373km
License Plate: JV91HRGP

Customer Information

Name: Dekra MFC AUCTION HOUSE
Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V13.70
Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(10)

System	Status/DTC
ENG (Engine)	 1
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 0
AB (Airbag)	 1
CLU (Cluster Module)	 0
I-TPMS (I-Tire Pressure Monitoring System)	 0
A/C (Air Conditioner)	 0
CODE (Transmitter Code Saving)	 0
EPS (Motor Driven Power Steering)	 1
IBU-BCM (Integrated Body Control Unit-Body Control Module)	 0
IBU-IMMO (Integrated Body Control Unit-Immobilizer)	 0

DTC (3)

ENG (Engine) (1 DTC)

DTC	Description	Status
P0638:00	Throttle actuator control range/performance	History

AB (Airbag) (1 DTC)

DTC	Description	Status
B1102:00	Battery voltage low	History

EPS (Motor Driven Power Steering) (1 DTC)



DTC	Description	Status
C1102:16	Battery voltage low	History

Technician Notes

2016439572

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.