



Shop: DEKRA MFC
Tel: --
Email: --
Address: MFC Auction House
Kempton Park

Report ID: MAXIA20240110095647
Test Time: 2024-01-10 09:56:47
Technician: Travino

Kia VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Kia/Rio/--

VIN: KNADN511LG6021332

Odometer Reading: 255451

License Plate: FP30KZGP

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01482

Version: V13.50

Repair Order Number: --

System Scanned(7)

System	Status/DTC
ENG (Engine)	 1
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 0
AB (Airbag)	 0
BCM (Body Control)	 0
IMMO (Immobilizer)	 0
CODE (Transmitter Code Saving)	 0
EPS (Motor Driven Power Steering)	 1

DTC (2)

ENG (Engine) (1 DTC)

DTC	Description	Status
P0014	Exhaust camshaft position (CMP) B timing over-Advanced or system performance (Bank 1)	Pending

EPS (Motor Driven Power Steering) (1 DTC)

DTC	Description	Status
C1259	Steering angle sensor (SAS) electrical fault	History



Technician Notes

2016223346

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.