



Shop: Dekra MFC
Tel: 0861033572
Email: --
Address: MFC Auction House
M57 Pretoria Road
Glen Marais
Kempton Park
1619

Report ID: MAXIA20231206115357
Test Time: 2023-12-06 11:53:57
Technician: Andrick

Kia VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Kia/Rio(UB)/--

VIN: KNADN511LG6056984

Odometer Reading: 119506

License Plate: FV93JYGP

Customer Information

Name: MFC MFC

Tel: 0000

Device information

Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01509

Version: V13.50

Repair Order Number: --

System Scanned(7)

System	Status/DTC
ENG (Engine)	 0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 0
AB (Airbag)	 2
BCM (Body Control)	 0
IMMO (Immobilizer)	 0
CODE (Transmitter Code Saving)	 0
EPS (Motor Driven Power Steering)	 0

DTC (2)

AB (Airbag) (2 DTCs)

DTC	Description	Status
B1102:00	Battery voltage low	History
B2500:00	Warning lamp failure	History



Technician Notes

2016191495

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.