

Shop: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20240723091629
Test Time: 2024-07-23 09:16:29
Technician: Andrick

GreatWall VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/GreatWall/Wingle 5/2011-2016(basic model)/--
VIN: LGWCA2174DC619388
Odometer Reading: 222446
License Plate: FP46XXGP


Customer Information

Name: Dekra MFC AUCTION HOUSE
Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V10.50
Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(1)

System	Status/DTC
ECM (Engine System)-Delphi MT20U2_EOBD engine system	 1

DTC (1)

ECM (Engine System)-Delphi MT20U2_EOBD engine system (1 DTC)

DTC	Description	Status
P0141	Downstream O2 Sensor Heater Fault	Current DTC

Technician Notes

2016464276

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

