

Maruti Suzuki VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Maruti Suzuki/Celerio/--
VIN: MA3KFC42S00516139

Odometer Reading: 121148
License Plate: KW27VJGP

Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V4.80

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (7)

System	Status/DTC
Engine/powertrain	 0
ABS/ESP	 5
Airbag	 0
Instrument Panel Cluster (IPC)/meter/M&A	 0
Power steering	 0
BCM	 1
Immobilizer and/or keyless system	 1

DTC (7)

ABS/ESP (5 DTCs)

DTC	Description	Status
C1032	Right rear Wheel Speed Sensor (WSS) or encoder signal performance	History
C1057	Power supply voltage	History
C1026	Left front Wheel Speed Sensor (WSS) or encoder signal performance	History
C1033	Wheel Speed Sensor (WSS) deviation	History
C1091	CAN invalid data from ECM	History

BCM (1 DTC)

DTC	Description	Status
B1188	Transponder communication fault	History

Immobilizer and/or keyless system (1 DTC)

DTC	Description	Status
B1188	Transponder communication fault	History

Technician Notes
2016999436

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.