



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250507131331
Test Time: 2025-05-07 13:13:31
Technician: Sbu

Maruti Suzuki VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Maruti Suzuki/S-presso/--
VIN: MA3RFL41S00372834

Odometer Reading: 144899
License Plate: NO r eg

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V4.70

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(7)

System	Status/DTC
Engine/powertrain	1
ABS/ESP	1
Airbag	0
Instrument Panel Cluster (IPC)/meter/M&A	1
Power steering	0
BCM	0
Immobilizer and/or keyless system	0

DTC (3)

Engine/powertrain (1 DTC)

DTC	Description	Status
P0136	Oxygen sensor circuit (bank 1 sensor 2)	History

ABS/ESP (1 DTC)

DTC	Description	Status
C1057	Power supply voltage	History

Instrument Panel Cluster (IPC)/meter/M&A (1 DTC)

DTC	Description	Status
B1810	Fuel level sensor circuit open	History

Technician Notes

2016867888



Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.