

# Honda VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Honda/Amaze/--

VIN: MAKDF5630K4000339

Odometer Reading: 191532km

License Plate: JK67XNGP

## Customer Information

Name: MFC Dekra Nedbank Auction House

Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01509

Version: V9.30

Repair Order Number: --

## System Scanned( 8 )

| System          | Status/DTC |
|-----------------|------------|
| Engine-PGM FI   | 0          |
| AT              | 0          |
| ABS/TCS/VSA     | 0          |
| SRS             | 0          |
| Gauges          | 0          |
| Body electrical | 0          |
| IMMOBI          | 0          |
| EPS             | 0          |

## DTC ( 0 )

## Technician Notes

2016395930

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note:Please save a copy of this report for your records.