



Shop Name: Dekra MFC Auction House  
Tel: --  
Email: --  
Address: MFC AUCTION HOUSE  
M57 PRETORIA ROAD  
KEMPTON PARK

Report ID: MAXIA20250423152241  
Test Time: 2025-04-23 15:22:41  
Technician: Sbu

# Hyundai VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Hyundai/Grand i10/Xcent (BA)/--  
VIN: MALA851CLGM457124

Odometer Reading: 166461  
License Plate: FL74VPGP

## Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

## Device information

Scanner: MaxiSys MS906 BT  
Version: V13.86

Serial Number: VB8GJCC01514  
Repair Order Number: --

## System Scanned( 8 )

System	Status/DTC
ENG (Engine)	<span>✓</span> 0
AB (Airbag)	<span>✗</span> 2
CLU (Cluster Module)	<span>✓</span> 0
IMMO (Immobilizer)	<span>✓</span> 0
CODE (Transmitter Code Saving)	<span>✓</span> 0
EPS (Motor Driven Power Steering)	<span>✓</span> 0
BCM (Body Control)	<span>✓</span> 0
SJB (Smart Junction Block)	<span>✗</span> 1

## DTC ( 3 )

### AB (Airbag) ( 2 DTCs )

DTC	Description	Status
B1102:00	Battery voltage low	History
B2500:00	Warning lamp failure	History

### SJB (Smart Junction Block) ( 1 DTC )

DTC	Description	Status
B2518:00	Left cornering lamp circuit short to ground	History

## Technician Notes

2016852390



Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.