



Shop: DEKRA MFC
Tel: --
Email: --
Address: MFC Auction House
Kempton Park

Report ID: MAXIA20231228114042
Test Time: 2023-12-28 11:40:42
Technician: Andrick

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/Santro (AH2)/--
VIN: MALAF51CLNM147116

Odometer Reading: 41842km
License Plate: KB66NXGP

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V13.40

Serial Number: VB8GJCC01482
Repair Order Number: --

System Scanned(6)

System	Status/DTC
ENG (Engine)	 0
ABS/ESC (Anti Lock Brake/Electronic Stability Control)	 0
AB (Airbag)	 0
CLU (Cluster Module)	 0
IMMO (Immobilizer)	 0
EPS (Motor Driven Power Steering)	 0

DTC (0)

Technician Notes

2016213106

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.

