

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/GRAND i10(AI3)/--
VIN: MALB251ALPM361565

Odometer Reading: 60026KM
License Plate: LH07TLGP

Customer Information

Name: MFC Dekra Nedbank Auction House












Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V13.90

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (11)

System	Status/DTC
ENG (Engine)	 0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 0
AB (Airbag)	 1
CLU (Cluster Module)	 0
IBU-TPMS (Integrated Body Control Unit-Tire Pressure Monitoring System)	 0
CODE (Transmitter Code Saving)	 0
EPS (Motor Driven Power Steering)	 0
IBU-BCM (Integrated Body Control Unit-Body Control Module)	 0
IBU-SMK (Integrated Body Control Unit-Smart Key Unit)	 0
IBU-IMMO (Integrated Body Control Unit-Immobilizer)	 0
ICU (Integrated Central Control Unit)	 4

DTC (5)

AB (Airbag) (1 DTC)

DTC	Description	Status
B1116:00	Battery voltage unstable	History

ICU (Integrated Central Control Unit) (4 DTCs)

DTC	Description	Status
B1102:00	Battery voltage low	History

B251D:00	Right stop lamp circuit short to ground	History
B251E:00	Left stop lamp circuit short to ground	History
B251F:00	High mounted stop lamp circuit short to ground	History

Technician Notes
2016997968

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.