Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/GRAND i10(AI3)/--
VIN: MALB251ALTM735560

Odometer Reading: 20417KM
License Plate: DK84PNZN

Customer Information

Name: MFC NEDBANK

Tel: 0118799321

Device Information

Scanner: MaxiSys MS906 BT
Version: V14.15

Serial Number: VB8GJCC01509
Repair Order Number: --

System Scanned (11)

System	Status/DTC
ENG (Engine)	0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	0
AB (Airbag)	1
CLU (Cluster Module)	0
IBU-TPMS (Integrated Body Control Unit-Tire Pressure Monitoring System)	0
CODE (Transmitter Code Saving)	0
EPS (Motor Driven Power Steering)	1
IBU-BCM (Integrated Body Control Unit-Body Control Module)	0
IBU-SMK (Integrated Body Control Unit-Smart Key Unit)	0
IBU-IMMO (Integrated Body Control Unit-Immobilizer)	0
ICU (Integrated Central Control Unit)	4

DTC (6)

AB (Airbag) (1 DTC)

DTC	Description	Status
B1102:00	Battery voltage low	History

EPS (Motor Driven Power Steering) (1 DTC)

DTC	Description	Status
C1102:16	Battery voltage low	History

ICU (Integrated Central Control Unit) (4 DTCs)

DTC	Description	Status
B1102:00	Battery voltage low	History
B258A:00	Right front external tail lamp circuit short to ground	History
B2602:00	Left headlamp low beam circuit open	History
B2603:00	Right headlamp low beam circuit open	History

Technician Notes

2017325967

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.