

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/i20(BI3)/--

VIN: MALBG512LNM069070

Odometer Reading: 75827km

License Plate: KD67WKGP

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT

Serial Number: VB8GJCC01482

Version: V13.40

Repair Order Number: --



System Scanned(13)

System	Status/DTC
ENG (Engine)	✓ 0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	✓ 0
AB (Airbag)	✗ 1
CLU (Cluster Module)	✓ 0
CODE (Transmitter Code Saving)	✓ 0
EPS (Motor Driven Power Steering)	✓ 0
AVN (Audio Video Navigation)	ADAS ✓ 0
IBU-BCM (Integrated Body Control Unit-Body Control Module)	✓ 0
IBU-TPMS (Integrated Body Control Unit-Tire Pressure Monitoring System)	✓ 0
IBU-SMK (Integrated Body Control Unit-Smart Key Unit)	✓ 0
IBU-IMMO (Integrated Body Control Unit-Immobilizer)	✓ 0
ICU (Integrated Central Control Unit)	✓ 0
RVM (Rear View Monitor)	ADAS ✓ 0



DTC (1)

AB (Airbag) (1 DTC)

DTC	Description	Status
-----	-------------	--------

B2617:00

Cluster airbag warning lamp CAN message timeout

History

Technician Notes

2016204818

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.