

Shop Name: Dekra MFC Auction House Tel: --Email: --Address: MFC AUCTION HOUSE M57 PRETORIA ROAD KEMPTON PARK Report ID: MAXIA20250516111323 Test Time: 2025-05-16 11:13:23 Technician: Sbu

# Hyundai VEHICLE DIAGNOSTIC REPORT

### **Vehicle Information**

--/Hyundai/i20(IB)/--VIN: MALBM51BLKM523930

#### **Customer Information**

Name: Dekra MFC AUCTION HOUSE

#### **Device information**

Scanner: MaxiSys MS906 BT Version: V13.86 Odometer Reading: 229904km License Plate: HN50CWGP

Tel: 0861033572

Serial Number: VB8GJCC01514 Repair Order Number: --

#### 🔁 System Scanned( 8 )

System	Status/DTC
ENG (Engine)	<b>O</b>
ABS (Anti Lock Brake)	<b>O</b>
AB (Airbag)	3 1
CLU (Cluster Module)	<b>O</b>
IMMO (Immobilizer)	<b>o</b>
CODE (Transmitter Code Saving)	<b>O</b>
EPS (Motor Driven Power Steering)	<b>O</b>
BCM (Body Control)	<b>O</b>

## 🔼 DTC (1)

### AB (Airbag) (1 DTC)

DTC	Description	Status
B1102:00	Battery voltage low	History

# Technician Notes 2016880319

Customer name:

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note:Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.