



Shop: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20240619065539
Test Time: 2024-06-19 06:55:39
Technician: Travino

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/i20(IB)/--
VIN: MALBM51CLHM350237
Odometer Reading: 114260
License Plate: HF78PSHP

Customer Information

Name: Dekra MFC AUCTION HOUSE
Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V13.70
Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(9)

System	Status/DTC
ENG (Engine)	0
ABS (Anti Lock Brake)	0
AB (Airbag)	0
CLU (Cluster Module)	0
IMMO (Immobilizer)	0
CODE (Transmitter Code Saving)	0
A/C (Air Conditioner)	0
EPS (Motor Driven Power Steering)	1
BCM (Body Control)	0

DTC (1)

EPS (Motor Driven Power Steering) (1 DTC)

DTC	Description	Status
C1259	Steering angle sensor (SAS) electrical fault	History



Technician Notes

2016421895

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.