# Hyundai VEHICLE DIAGNOSTIC REPORT

## Vehicle Information

--/Hyundai/i20(IB)/--
VIN: MALBM51CMKM634073

Odometer Reading: 314148KM
License Plate: HW56DTGP

## Customer Information

Name: MFC NEDBANK

Tel: 0118799321

## Device Information

Scanner: MaxiSys MS906 BT
Version: V14.15

Serial Number: VB8GJCC01509
Repair Order Number: --

## System Scanned ( 10 )

| System | Status/DTC |
|---|---|
| ENG (Engine) | 0 |
| A/T (Transaxle) | 0 |
| ABS (Anti Lock Brake) | 0 |
| AB (Airbag) | 1 |
| CLU (Cluster Module) | 0 |
| A/C (Air Conditioner) | 1 |
| IMMO (Immobilizer) | 0 |
| CODE (Transmitter Code Saving) | 0 |
| EPS (Motor Driven Power Steering) | 0 |
| BCM (Body Control) | 0 |

## DTC ( 2 )

### AB (Airbag) ( 1 DTC )

| DTC | Description | Status |
|---|---|---|
| B1102:00 | Battery voltage low | History |

### A/C (Air Conditioner) ( 1 DTC )

| DTC | Description | Status |
|---|---|---|
| B1688 | A/C ionizer fault | Active |

## Technician Notes

2017324443

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.

*Disclaimer: This report provides a reference for vehicle inspection and maintenance only. Autel is not liable for any accident, property damage, or personal injury resulting from the use of this information.*