



Shop: DEKRA MFC
Tel: --
Email: --
Address: MFC Auction House
Kempton Park

Report ID: MAXIA20231227140325
Test Time: 2023-12-27 14:03:25
Technician: Werner

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/Creta (GS)/--
VIN: MALC381CLLM656582

Odometer Reading: 57021km
License Plate: JP12VGGP

Customer Information

Name: DEKRA AUTOMATIC MFC MFC AUCTION HOUSE







Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V13.40

Serial Number: VB8GJCC01482
Repair Order Number: --

System Scanned(9)

System	Status/DTC
ENG (Engine)	 0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 0
AB (Airbag)	 0
CLU (Cluster Module)	 0
IMMO (Immobilizer)	 0
CODE (Transmitter Code Saving)	 0
EPS (Motor Driven Power Steering)	 0
BCM (Body Control)	 0
SJB (Smart Junction Block)	 0

DTC (0)

Technician Notes

2016212397

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.