



Shop Name: Dekra MFC Auction House
Tel: --
Email: --
Address: MFC AUCTION HOUSE
M57 PRETORIA ROAD
KEMPTON PARK

Report ID: MAXIA20250625150541
Test Time: 2025-06-25 15:05:41
Technician: Andrick

Hyundai VEHICLE DIAGNOSTIC REPORT

Vehicle Information

--/Hyundai/VENUE(QXI)/--
VIN: MALFC81AVMM169346

Odometer Reading: 66949km
License Plate: JZ89RRGP

Customer Information

Name: Dekra MFC AUCTION HOUSE

Tel: 0861033572

Device information

Scanner: MaxiSys MS906 BT
Version: V13.87

Serial Number: VB8GJCC01514
Repair Order Number: --

System Scanned(14)

System	Status/DTC
ENG (Engine)	 0
A/T (Transaxle)	 0
ABS/ESP (Anti Lock Brake/Electronic Stability Program)	 0
AB (Airbag)	 1
CLU (Cluster Module)	 0
IBU-TPMS (Integrated Body Control Unit-Tire Pressure Monitoring System)	 0
CODE (Transmitter Code Saving)	 0
A/C (Air Conditioner)	 0
EPS (Motor Driven Power Steering)	 1
IBU-BCM (Integrated Body Control Unit-Body Control Module)	 0
IBU-SMK (Integrated Body Control Unit-Smart Key Unit)	 0
IBU-IMMO (Integrated Body Control Unit-Immobilizer)	 0
ICU (Integrated Central Control Unit)	 0
IMT (Intelligent Manual Transmission)	 0

DTC (2)

AB (Airbag) (1 DTC)



DTC	Description	Status
B1346:00	Driver airbag (DAB) resistance too high (1st Stage)	History

EPS (Motor Driven Power Steering) (1 DTC)

DTC	Description	Status
C1102:16	Battery voltage low	History

Technician Notes
2016925114

Customer name: _____

Technician: _____

Date: _____

Note:Please save a copy of this report for your records.